IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant	: Adrian J. Drexler	Attorney Docket No.:	501112.01
Patent No.	: US 6,988,218 B2	Serial No.	: 10/074,296
Issue Date	: January 17, 2006	Filed	: February 11, 2002
Title	: SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL		

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

A Certificate of Correction under 35 U.S.C. § 254 is respectfully requested for the above-identified patent in order to correct Patent and Trademark Office errors made during the printing of the patent. The changes in the patent needed to correct the errors are as follows:

Column, Line	Reads	Should Read
Item (54)	"SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL BY SELECTIVELY LOCKING DELAY INTERVAL"	--SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL--
Column 1, Lines 1-4	"SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP	--SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL--

CONTROL BY
SELECTIVELY LOCKING
DELAY INTERVAL"

Column 1, Line 10	"delay locked look"	--delay locked loop--
Column 3, Line 32	"recognize that,"	--recognize that--
Column 3, Line 39	"known that, to enable"	--know that to enable--
Column 3, Line 41	"is driven high, that the"	--is driven high, the--
Column 3, Line 55	"will not need not be actively"	--will not need to be actively--
Column 4, Line 25	"and/or disable"	--and/or disabling--
Column 4, Line 35	"device 100, may be"	--device 100 may be--
Column 4, Lines 54-57	"At that point, if no data is being written to or received by the DRAM device, and there is no need for the DLL 110 to continue switching to fine tune its synchronization with the system clock."	--At that point, if no data is being written to or received by the DRAM device, there is no need for the DLL 110 to continue switching to fine tune its synchronization with the system clock.--
Column 4, Line 63	"FIG. 2 is block diagram"	--FIG. 2 is a block diagram--
Column 5, Line 48	"in at attempt"	--in an attempt--
Column 5, Lines 54-55	"By locking in the delay interval in place once the DRAM device"	--Locking the delay interval in place once the DRAM device--
Column 6, Line 5	"later saves power"	--latter saves power--
Column 8, Line 24	"from the a time the command"	--from a time the command--
Column 8, Line 57	"from the a time the command"	--from a time the command--
Column 9, Line 9	"responsive to command"	--responsive to a command--
Column 9, Line 65	"DRAM devices the computer"	--DRAM devices of the computer--

Column 10, Line 3   "to command"   --to a command--

        The above errors for which correction is requested under 35 U.S.C. § 254 were made in the printing of the patent or in the original application. The errors are considered sufficiently important to justify the processing of a Certificate of Correction under 35 U.S.C. § 254. A Form PTO-1050, in duplicate, is enclosed herewith.

        The Commissioner is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 50-1266. A duplicate copy of this sheet is enclosed.

        Favorable consideration of this Request is respectfully requested.

                                  Respectfully submitted,

Date: _October 26, 2007_   By: _____

                                 Edward W. Bulchis, Reg. No. 26,847
                                 Customer No. 27,076
                                 Dorsey & Whitney LLP
                                 1420 Fifth Avenue, Suite 3400
                                 Seattle, WA 98101
                                 (206) 903-8785
                                 Attorney for Applicant(s)

EWB:tdp

Enclosures:
    Postcard
    Form PTO-1050 (+ copy)

501112.01 req cert correct

MAY 7 2007

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO.   :   US 6,988,218 B2
DATED   :   January 17, 2006
INVENTOR(S)   :   Adrian J. Drexler

It is certified that errors appear in the above identified patent and that said Letters Patent is hereby corrected as shown below:

Column, Line	Reads	Should Read
Item (54)	"SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL BY SELECTIVELY LOCKING DELAY INTERVAL"	--SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL--
Column 1, Lines 1-4	"SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL BY SELECTIVELY LOCKING DELAY INTERVAL"	--SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL--
Column 1, Line 10	"delay locked look"	--delay locked loop--
Column 3, Line 32	"recognize that,"	--recognize that--
Column 3, Line 39	"known that, to enable"	--know that to enable--
Column 3, Line 41	"is driven high, that the"	--is driven high, the--
Column 3, Line 55	"will not need not be actively"	--will not need to be actively--
Column 4, Line 25	"and/or disable"	--and/or disabling--
Column 4, Line 35	"device **100**, may be"	--device **100** may be--

| Column 4, Lines 54-57	"At that point, if no data is being written to or received by the DRAM device, and there is no need for the DLL **110** to continue switching to fine tune its synchronization with the system clock."	--At that point, if no data is being written to or received by the DRAM device, there is no need for the DLL **110** to continue switching to fine tune its synchronization with the system clock.--
Column 4, Line 63	"FIG. **2** is block diagram"	--FIG. **2** is a block diagram--
Column 5, Line 48	"in at attempt"	--in an attempt--
Column 5, Lines 54-55	"By locking in the delay interval in place once the DRAM device"	--Locking the delay interval in place once the DRAM device--
Column 6, Line 5	"later saves power"	--latter saves power--
Column 8, Line 24	"from the a time the command"	--from a time the command--
Column 8, Line 57	"from the a time the command"	--from a time the command--
Column 9, Line 9	"responsive to command"	--responsive to a command--
Column 9, Line 65	"DRAM devices the computer"	--DRAM devices of the computer--
Column 10, Line 3	"to command"	--to a command--

MAILING ADDRESS OF SENDER:

DORSEY & WHITNEY LLP
1420 Fifth Avenue, Suite 3400
Seattle, Washington 98101

Patent No. US 6,988,218 B2

No. add'l. copies
@ .30 per page
➔_____

FORM PTO-1050 (REV. 3-82)
501112.01 PTO 1050

I hereby certify that on the date specified below, this correspondence is being deposited with the United States Postal Service as first-class mail in an envelope addressed to the Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

Oct. 30, 2007   _Beverly Loken_

Date   Beverly Loken

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant	: Adrian J. Drexler	Attorney Docket No.:	501112.01
Patent No.	: US 6,988,218 B2	Serial No.	: 10/074,296
Issue Date	: January 17, 2006	Filed	: February 11, 2002
Title	: SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL		

<u>REQUEST FOR CERTIFICATE OF CORRECTION</u>

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

      A Certificate of Correction under 35 U.S.C. § 254 is respectfully requested for the above-identified patent in order to correct Patent and Trademark Office errors made during the printing of the patent. The changes in the patent needed to correct the errors are as follows:

<u>Column, Line</u>	<u>Reads</u>	<u>Should Read</u>
Item (54)	"SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL BY SELECTIVELY LOCKING DELAY INTERVAL"	--SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL--
Column 1, Lines 1-4	"SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP	--SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL--

CONTROL BY
SELECTIVELY LOCKING
DELAY INTERVAL"

Column 1, Line 10	"delay locked look"	--delay locked loop--
Column 3, Line 32	"recognize that,"	--recognize that--
Column 3, Line 39	"known that, to enable"	--know that to enable--
Column 3, Line 41	"is driven high, that the"	--is driven high, the--
Column 3, Line 55	"will not need not be actively"	--will not need to be actively--
Column 4, Line 25	"and/or disable"	--and/or disabling--
Column 4, Line 35	"device **100**, may be"	--device **100** may be--
Column 4, Lines 54-57	"At that point, if no data is being written to or received by the DRAM device, and there is no need for the DLL **110** to continue switching to fine tune its synchronization with the system clock."	--At that point, if no data is being written to or received by the DRAM device, there is no need for the DLL **110** to continue switching to fine tune its synchronization with the system clock.--
Column 4, Line 63	"FIG. **2** is block diagram"	--FIG. **2** is a block diagram--
Column 5, Line 48	"in at attempt"	--in an attempt--
Column 5, Lines 54-55	"By locking in the delay interval in place once the DRAM device"	--Locking the delay interval in place once the DRAM device--
Column 6, Line 5	"later saves power"	--latter saves power--
Column 8, Line 24	"from the a time the command"	--from a time the command--
Column 8, Line 57	"from the a time the command"	--from a time the command--
Column 9, Line 9	"responsive to command"	--responsive to a command--
Column 9, Line 65	"DRAM devices the computer"	--DRAM devices of the computer--

NOV 7 2007

Column 10, Line 3   "to command"   --to a command--

The above errors for which correction is requested under 35 U.S.C. § 254 were made in the printing of the patent or in the original application. The errors are considered sufficiently important to justify the processing of a Certificate of Correction under 35 U.S.C. § 254. A Form PTO-1050, in duplicate, is enclosed herewith.

The Commissioner is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 50-1266. A duplicate copy of this sheet is enclosed.

Favorable consideration of this Request is respectfully requested.

Respectfully submitted,

Date: _October 26, 2007_   By: _____
                                  Edward W. Bulchis, Reg. No. 26,847
                                  Customer No. 27,076
                                  Dorsey & Whitney LLP
                                  1420 Fifth Avenue, Suite 3400
                                  Seattle, WA 98101
                                  (206) 903-8785
                                  Attorney for Applicant(s)

EWB:tdp

Enclosures:
    Postcard
    Form PTO-1050 (+ copy)

501112.01 req cert correct

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO.   :   US 6,988,218 B2
DATED   :   January 17, 2006
INVENTOR(S)   :   Adrian J. Drexler

It is certified that errors appear in the above identified patent and that said Letters Patent is hereby corrected as shown below:

Column, Line	Reads	Should Read
Item (54)	"SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL BY SELECTIVELY LOCKING DELAY INTERVAL"	--SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL--
Column 1, Lines 1-4	"SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL BY SELECTIVELY LOCKING DELAY INTERVAL"	--SYSTEM AND METHOD FOR POWER SAVING DELAY LOCKED LOOP CONTROL--
Column 1, Line 10	"delay locked look"	--delay locked loop--
Column 3, Line 32	"recognize that,"	--recognize that--
Column 3, Line 39	"known that, to enable"	--know that to enable--
Column 3, Line 41	"is driven high, that the"	--is driven high, the--
Column 3, Line 55	"will not need not be actively"	--will not need to be actively--
Column 4, Line 25	"and/or disable"	--and/or disabling--
Column 4, Line 35	"device **100**, may be"	--device **100** may be--

NOV 7 2007

Column 4, Lines 54-57	"At that point, if no data is being written to or received by the DRAM device, and there is no need for the DLL **110** to continue switching to fine tune its synchronization with the system clock."	--At that point, if no data is being written to or received by the DRAM device, there is no need for the DLL **110** to continue switching to fine tune its synchronization with the system clock.--
Column 4, Line 63	"FIG. **2** is block diagram"	--FIG. **2** is a block diagram--
Column 5, Line 48	"in at attempt"	--in an attempt--
Column 5, Lines 54-55	"By locking in the delay interval in place once the DRAM device"	--Locking the delay interval in place once the DRAM device--
Column 6, Line 5	"later saves power"	--latter saves power--
Column 8, Line 24	"from the a time the command"	--from a time the command--
Column 8, Line 57	"from the a time the command"	--from a time the command--
Column 9, Line 9	"responsive to command"	--responsive to a command--
Column 9, Line 65	"DRAM devices the computer"	--DRAM devices of the computer--
Column 10, Line 3	"to command"	--to a command--

MAILING ADDRESS OF SENDER:

DORSEY & WHITNEY LLP
1420 Fifth Avenue, Suite 3400
Seattle, Washington 98101

Patent No. US 6,988,218 B2

No. add'l. copies
@ .30 per page
➔ _____

FORM PTO-1050 (REV. 3-82)
501112.01 PTO 1050